DV: Device S: Sensors AST: Acquisition start time AET: Acquisition end time SF: Sampling frequency MU: Unit of measurement DT DT: Delta time between data points PT: Post time MAC: Machine MOD: Sensor's model LOC: Sensor's location DATA KPI: Key performance indicator RMS MAC AET Time VAR MOD AST DVLOC . . . PT KPI AI 1 SF MU Frequency S AI 2