
UAV-edge processing · controlled mission-information staleness
Perfect communication
Stale A*
Stale intentions
Stale priorities
All stale
Stage 1
Stage 2
Stage 3
Stage 4
Failure-aware PAR-2 (steps)
Additional controlled delay (steps)
1
2
5
10
20
22.5
23.0
23.5
24.0
24.5
37
38
39
40
55
60
65
70
45
50
55
60
65