



Repair Estimate

Diagnostic & Injector Replacement

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0002

STATUS

ESTIMATE

ESTIMATE DATE

10 April 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

Customer

SERVICE ADDRESS

Customer location

Vehicle: 2022 Mercedes-Benz Sprinter 2.1 4x4 (OM651) (TBC) **Odometer:** - **Job ID:** EST-2026-0002 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
STAGE 1 – ON-SITE DIAGNOSTIC CALLOUT			
Mobile Diagnostic Callout – Rough Running / EML			
2022 Mercedes Sprinter 2.1 4x4 Campervan (OM651)			
Suspected injector / wiring fault.	1 hr	£130.00	£130.00
Full-system diagnostic scan, live data analysis, injector deviation test, wiring checks, guided fault-finding, and written diagnostic report.			
		VAT (20%)	£26.00
Vehicle Health Check			
Complimentary multi-point vehicle health check included with diagnostic visit.	1	FOC	FREE
Covers all major systems: engine, transmission, brakes, suspension, electrics.			
STAGE 2 – REPAIR ESTIMATE (IF INJECTOR CONFIRMED FAULTY)			
Parts: Genuine Mercedes Injector for Common Rail			
Part No. A651 070 30 87	1	£275.00	£275.00
Genuine Mercedes-Benz fuel injector – OM651 engine.			
Parts: Injector Washer			
Part No. A611 017 00 60	1	£1.10	£1.10
Parts: Spherical Collar			
Part No. A001 990 26 07	1	£3.25	£3.25
		Parts VAT (20%)	£55.87
Labour: Injector Replacement & Coding (1 hr @ £85 + VAT)			
Remove and replace fuel injector, perform quick test, clear faults and verify operation.	1 hr	£85.00	£85.00
		Labour VAT (20%)	£17.00
XENTRY LABOUR BREAKDOWN (1.0 HRS TOTAL)			
07-6929	Replace one fuel injector (after check)		0.8 H
54-1011	Perform quick test		0.2 H

Subtotal	£494.35
Discount	£0.00
VAT (20%)	£98.87

Total	£593.22
Amount paid	£0.00
Balance due	£593.22

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the visit.

Stage 1 – Diagnostic Callout (Zone B): £156.00 inc. VAT

Payable on arrival. Includes vehicle health check.

Stage 2 – Injector Repair (if needed): £437.22 inc. VAT

Only proceeds with your authorisation after diagnostic results.

Notes: This is a two-stage estimate. Stage 1 (diagnostic) is confirmed and payable on arrival. Stage 2 (injector replacement) will only proceed with your authorisation after diagnosis. All genuine Mercedes-Benz parts carry a 2-year manufacturer warranty. Repair labour times are based on manufacturer standard times (XENTRY).

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.