



Repair Estimate

Engine ECU & Fuel Pipe Replacement

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0005

STATUS

ESTIMATE

ESTIMATE DATE

13 April 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

Evans Halshaw Ford Blackpool
mark.dorrans@evanshalshaw.com
01253 699000

SERVICE ADDRESS

Customer location

FAO: Mark Dorrans, Used Car Sales Leader
Vicarage Lane, Welbeck Avenue
Blackpool, FY4 4ES

Vehicle: Mercedes-Benz (GL64OJB) **Odometer:** - **Job ID:** EST-2026-0005 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS (GENUINE MERCEDES & BOSCH)			
Bosch Engine ECU (A2749000800) Refurbished unit supplied with a 1-year warranty.	1	£505.00	£505.00
Genuine Mercedes Fuel Pipe (A2740703500)	1	£36.03	£36.03
Genuine Mercedes Clamps	2	£1.74	£3.48
LABOUR & PROGRAMMING			
ECU Virginisation, SCN Coding & Installation Programming of replacement engine control unit to vehicle via XENTRY.	1	£80.00	£80.00
Mechanical Labour (HPFP & Lines) Replace fuel pipe, remove and reinstall high-pressure fuel pump (HPFP), replace seal if required.	3 hrs	£85.00	£255.00

Subtotal	£879.51
Discount	None
VAT (20%)	£175.90
Total	£1055.41
Amount paid	£0.00
Balance due	£1055.41

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repairs.

Vehicle Owner (On Record): Harry Richards, 98 Glenhurst Avenue, Bexley, DA5 3QN (s.richards98@ntlworld.com)

Notes: Estimate based on refurbished Bosch ECU (1-year warranty) and genuine Mercedes-Benz mechanical parts.

