



Service Invoice

Diagnostic visit completion

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0002

STATUS

PAID

INVOICE DATE

2 March 2026

DUE DATE

2 March 2026

PAYMENT TERMS

Due on receipt

BILL TO

Tom Wilson

SERVICE ADDRESS

23 New Road

Hextable

BR8 7LS

23 New Road

Hextable

BR8 7LS

Vehicle: 2016 Mercedes-Benz Vito W447 (DA16ZGO) **Odometer:** - **Job ID:** TPD-2026-0002 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
Diagnostic Callout – Intermittent Ignition Fault			
2016 Mercedes Vito W447 (DA16ZGO)			
Customer complaint: Ignition won't turn on in the mornings – has progressed and is now intermittent.	1	£120.00	£120.00
Full-system diagnostic scan, live data analysis, guided fault-finding, and written outcome report.			

Subtotal	£120.00
Discount	None
VAT (N/A – below VAT threshold)	£0.00
Total	£120.00
Amount paid	£120.00
Balance due	£0.00

Payment

Settled.

Bank transfer:

Tripoint Diagnostics Ltd

Sort code: 04-06-05

Account: 45761336

Reference: TPD-2026-0002

✓ Paid in full – thank you!

Notes: Standard diagnostic callout (£120.00) paid 2 March 2026. Follow-up EZS repair invoiced separately (see TPD-2026-0009).