



Service Invoice

Diagnostic visit completion

Tripont Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0003

STATUS

PAID

INVOICE DATE

7 March 2026

DUE DATE

14 March 2026

PAYMENT TERMS

Due on receipt

BILL TO

Tom Wilson

SERVICE ADDRESS

23 New Road

Hextable

BR8 7LS

23 New Road

Hextable

BR8 7LS

Vehicle: 2016 Mercedes-Benz Vito W447 (DA16ZGO) **Odometer:** - **Job ID:** TPD-2026-0003 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
Follow-Up Visit – EIS Collection & Repair			
2016 Mercedes Vito W447 (DA16ZGO)			
Travel to and from customer location, collected original EIS unit from vehicle.	1.5 hrs	£85.00/hr	£127.50
Taken back to unit for bench repair. Swapped common failure points: induction coil, IR reader, reflowed main IMU/processor.			
Donor EIS Unit (Parts)			
Donor Electronic Ignition Switch used for replacement components.	1	£120.00 £90.00	£90.00
<i>Reduced from £120.00</i>			

Subtotal	£217.50
Discount	None
VAT (N/A – below VAT threshold)	£0.00
Total	£217.50
Amount paid	£217.50
Balance due	£0.00

Payment

Settled.

Bank transfer:

Tripoint Diagnostics Ltd

Sort code: 04-06-05

Account: 45761336

Reference: TPD-2026-0003

✓ Paid in full via Stripe – thank you!

Notes: EZS/EIS repair follow-up from diagnostic visit (TPD-2026-0002). Balance of £217.50 paid via Stripe 7 March 2026. Invoice settled in full.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.

