



Service Invoice

Service B – eSprinter (W910)

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0007

STATUS

PAID

INVOICE DATE

11 April 2026

DUE DATE

18 April 2026

PAYMENT TERMS

Net 7 days

BILL TO

Family Action FOOD Clubs

SERVICE ADDRESS

Customer premises, London

07966 465611

34 Wharf Rd

London N1 7GR

Attn: Sylvia Barnes

FOOD Club Co-ordinator, Greenwich

Vehicle: Mercedes-Benz eSprinter (W910) (YF71 SGZ) **Odometer:** 4,421 km **Job ID:** TPD-008 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
Service B – Mercedes-Benz eSprinter (W910) Full Service B carried out in accordance with Mercedes-Benz and TriPoint Diagnostics procedures. Includes: full-system diagnostic scan (XENTRY), service reminder reset, HV battery health assessment (98% SOH), tyre tread & pressure check (TPMS reset), brake pad & disc measurement, visual health check (VHC), all fluid levels checked & topped up, cabin filter replacement, key battery replacement, wiper blade inspection, final quick test and written diagnostic service report. All parts and consumables are genuine Mercedes.			
	1 hr	£85.00	£85.00
PARTS & CONSUMABLES (GENUINE MERCEDES)			
Genuine Mercedes Key Battery 50% OFF Replacement key fob battery fitted during service.	1	£15.00 £7.50	£7.50
Genuine Mercedes Cabin Air (Dust) Filter 50% OFF Genuine filter inspected for debris/blockage and replaced.	1	£39.00 £19.50	£19.50
Brake Fluid (Genuine Mercedes) 50% OFF Full brake fluid replacement using Genuine Mercedes fluid.	1	£24.00 £12.00	£12.00
Screen Wash (Genuine Mercedes) 50% OFF Screen wash topped up to maximum.	1	£9.00 £4.50	£4.50
Coolant Top-Up (Genuine Mercedes) 50% OFF Coolant checked and topped up to MAX with genuine Mercedes coolant.	1	£7.34 £3.67	£3.67

Subtotal	£132.17
Discount	Applied directly to parts
VAT (20%)	£26.43
Total	£158.60
Amount paid	£158.60
Balance due	£0.00

Payment

Pay securely online via the link below, or by bank transfer.

Bank transfer:

Tripoint Diagnostics Ltd

Sort code: 04-06-05

Account: 45761336

Reference: TPD-2026-0007

✓ Paid in full – thank you!

Notes: Service B completed 10 April 2026. Full diagnostic service report with photographs, measurements and XENTRY printouts provided separately. Advisory noted: broken or missing connector for one interior light in load compartment.

Charity Discount Applied: As Family Action FOOD Clubs is a charity, TriPoint Diagnostics has applied a **50% discount on all parts and consumables**. The remaining 50% is subsidised by TriPoint Diagnostics.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.