



Service Invoice

Diagnostic visit completion

Tripont Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0010

STATUS

PAID

INVOICE DATE

14 April 2026

DUE DATE

14 April 2026

PAYMENT TERMS

Due on receipt

BILL TO

Aaron Upane
anyaupane@hotmail.com

SERVICE ADDRESS

Charlton, London SE7

Charlton

London SE7

Vehicle: Mercedes-Benz CLA (KM21 JUK) **Odometer:** - **Job ID:** TPD-2026-0010 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS			
Steering Column Switch Assembly (Wiper Stalk)			
Mercedes-Benz CLA (KM21 JUK)	1	£254.00	£254.00
Replacement steering column switch assembly including wiper stalk.			
LABOUR			
Mobile Callout & Installation			
Travel to customer location (Charlton, SE7), removal of old switch assembly, fitment of replacement, functional test and calibration.	1	£121.00	£121.00

Subtotal	£375.00
Discount	None
VAT (20%)	£75.00
Total	£450.00
Amount paid	£450.00
Balance due	£0.00

Payment

Settled.

Bank transfer:

Tripoint Diagnostics Ltd

Sort code: 04-06-05

Account: 45761336

Reference: TPD-2026-0010

✓ Paid in full – thank you!

Notes: £30.00 deposit paid via Stripe on 13 April 2026. Remaining balance of £420.00 paid 14 April 2026. Invoice settled in full.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.

