



Service Invoice

Diagnostic visit completion

Tripont Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0011

STATUS

PAID

INVOICE DATE

15 April 2026

DUE DATE

15 April 2026

PAYMENT TERMS

Due on receipt

BILL TO

David

leytonpolishcraft@gmail.com

SERVICE ADDRESS

Customer location

RM1 4XR

Vehicle: 2017 Mercedes-Benz GLA 200 AMG Line Premium Plus (AD17 BJX) **Odometer:** - **Job**
ID: TPD-2026-0011 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS			
Ignition Coil (Coilpack)			
Mercedes-Benz GLA 200 AMG Line Premium Plus (AD17 BJX)	2	£56.72	£113.44
Replacement ignition coils.			
LABOUR			
Mobile Callout & Coilpack Replacement			
Travel to customer location, removal of engine cover, replacement of 2x ignition coils, post-repair functional check & fault code clearing.	1	£158.23	£158.23

Subtotal	£271.67
Discount	None
VAT (20%)	£54.33
Total	£326.00
Amount paid	£326.00
Balance due	£0.00

Payment

Settled.

Bank transfer:

Tripoint Diagnostics Ltd

Sort code: 04-06-05

Account: 45761336

Reference: TPD-2026-0011

✓ Paid in full – thank you!

Notes: Follow-up repair from diagnostic visit (TPD-2026-0009). 2x coilpack replacement completed. Payment received 15 April 2026. Invoice settled in full.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.

