



Invoice

OSR Outer CV Boot Replacement

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0023

STATUS

UNPAID

INVOICE DATE

3 May 2026

DUE DATE

3 May 2026

PAYMENT TERMS

Due on receipt

BILL TO

Denise Harrild

SERVICE ADDRESS

Customer location

7 Coppergate
Hempstead
Gillingham, Kent
ME7 3QN

Vehicle: Mercedes-Benz V-Class W447 (Marco Polo) (K9 DDH) **Odometer:** - **Job ID:** TPD-2026-0023 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS			
Genuine Mercedes CV Boot Repair Kit Outer CV joint repair kit for OSR (Off-Side Rear) half shaft.	1	£28.49	£28.49
LABOUR			
Mobile Callout & CV Boot Installation Travel to customer location and remove/refit outer CV boot on OSR half shaft (approx. 45 mins).	1	£85.00	£85.00

Subtotal	£113.49
Discount	-£17.00 (20% off labour)
VAT (20%)	£19.30
Total	£115.79
Amount paid	£0.00
Balance due	£115.79

Payment

Bank transfer or card payment via secure link.

Bank transfer:

Tripoint Diagnostics Ltd
 Sort code: 04-06-05
 Account: 30447065
 Reference: TPD-2026-0023

[Pay £115.79 Online →](#)

Notes: Outer CV boot replaced on 3 May 2026 as per Estimate EST-2026-0010. 20% discount applied on labour.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.