



Invoice

Mercedes-Benz Service B Major Service

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0027

STATUS

PAID

INVOICE DATE

13 May 2026

DUE DATE

N/A

PAYMENT TERMS

Paid on completion

BILL TO

Gary Bingham (Creative Building Services Ltd)

SERVICE ADDRESS

Nursery Lodge
Pleasant Valley Lane
ME15 0BB

Creative Building Services Ltd

Nursery Lodge

Pleasant Valley Lane

ME15 0BB

Vehicle: Mercedes-Benz (FD68 FTX) **Odometer:** - **Job ID:** TPD-2026-0027 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS & CONSUMABLES (GENUINE MERCEDES & OE-GRADE FLUIDS)			
Genuine Mercedes-Benz Engine Oil 5W-30 (MB 229.52) Fully synthetic, low-SAPS, OEM-branded oil. Priced per litre.	12 L	£10.50 / L	£126.00
Genuine Mercedes Oil Filter Element & Seal Kit OE oil filter cartridge with new housing O-rings.	1	£18.00	£18.00
Sump Plug Crush Washer Single-use aluminium crush washer.	1	£3.50	£3.50
Genuine Mercedes Air Filter Element OE engine air filter.	1	£32.00	£32.00
Genuine Mercedes Diesel Fuel Filter OE in-line fuel filter element. Supplied with new O-ring seals.	1	£55.00	£55.00
Screen Wash Concentrate Top-up of windscreen washer reservoir.	1	£6.00	£6.00
LABOUR			
Mobile Service Callout (includes first hour labour) Travel to customer location, vehicle preparation, on-site Mercedes-Benz Service B (oil & filter change, air filter, fuel filter, coolant & screen-wash check), XENTRY quick test (full multi-module fault check), full service schedule (brake inspection, fluid checks, tyres, lights, wipers) and ASSYST B service indicator reset.	1 hr	£120.00	£120.00
Additional Labour Service B labour beyond the included first hour, billed at the standard hourly rate of £85.00 + VAT.	2.5 hrs	£85.00	£212.50
Parts + Labour subtotal (ex VAT)			£573.00
Service B fixed-price package adjustment			-£205.90
Net service charge (ex VAT)			£367.10

Subtotal	£367.10
Discount	Applied inline (Service B package, cabin filter not fitted)

VAT (20%)	£73.42
Total	£440.52
Amount paid	£440.52
Balance due	£0.00

Payment

Settled.

✓ Paid in full by Mastercard debit •••• 1120 on 13 May 2026 at 18:13. Thank you!

Stripe payment ID: pi_3TWgLJRzswjZPkV0AhWtZ69

Work completed today (Mercedes-Benz Service B): Engine oil & genuine Mercedes oil filter replaced; air filter replaced; fuel filter replaced; screen wash topped up; coolant level checked and topped up; XENTRY quick test (full multi-module fault check); full Mercedes-Benz service schedule (brake inspection, fluid checks, tyres, lights and wipers); ASSYST B service indicator reset.

Cabin filter: Not fitted on this vehicle. Cabin filter portion of the quoted package not supplied or charged.

Pricing: Parts and labour itemised above at standard list rates, with the Service B fixed-price package adjustment applied inline to reach the agreed bundled service price.

Payment: £440.52 received in full on 13 May 2026 at 18:13 via Stripe (Mastercard debit •••• 1120, Metro Bank PLC). Invoice settled.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.