



Estimate

Auxiliary Belt & Tensioner Replacement (FEBI Aftermarket)

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0015

STATUS

ESTIMATE

ESTIMATE DATE

19 May 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

Tom Millen (Archie's Castles & Soft Play)

SERVICE ADDRESS

Fermain, The Street
Sittingbourne, ME9 8JN

Fermain
The Street
Sittingbourne, Kent
ME9 8JN

Vehicle: Mercedes-Benz Sprinter (KR70 PWE) **Odometer:** - **Job ID:** EST-2026-0015 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS (FEBI BILSTEIN - OE-QUALITY AFTERMARKET)			
FEBI V-ribbed Belt Tensioner Part No. FEB177942 OE-quality aftermarket auxiliary-belt tensioner assembly. Supplied at £77.26 inc VAT (£64.38 ex VAT).	1	£64.38	£64.38
FEBI V-ribbed Belt Part No. FEB28925 OE-quality aftermarket multi-rib (poly-V) auxiliary drive belt. Supplied at £10.38 inc VAT (£8.65 ex VAT).	1	£8.65	£8.65
LABOUR			
Mobile Callout Standard mobile callout fee waived as a thank-you for repeat business.	1	£120.00	WAIVED
Auxiliary Belt & Tensioner Replacement Remove and replace auxiliary (poly-V) drive belt and belt tensioner assembly, inspect pulleys, refit and verify operation. Charged at the standard hourly rate of £85.00 + VAT per XENTRY manufacturer times.	0.9 hrs	£85.00	£76.50
XENTRY LABOUR BREAKDOWN (0.9 HRS TOTAL)			
13-1202	Replace V-belt on vehicle with single-belt drive		0.7 H
13-3209	Remove/install tensioning device for V-belt, replace assembly parts if necessary (V-belt removed)		0.2 H

Subtotal	£149.53
Discount	Mobile callout waived (repeat customer)
VAT (20%)	£29.91
Total	£179.44
Amount paid	£0.00
Balance due	£179.44

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repair.

Scope: Follow-up visit to replace the auxiliary (poly-V) drive belt and belt tensioner assembly on the Mercedes-Benz Sprinter (KR70 PWE). Pulleys will be inspected while accessible.

Parts: FEBI Bilstein OE-quality aftermarket parts. FEBI is a respected German OE supplier widely used by independent specialists; their parts are manufactured to OE specification and typically come with a 2-year warranty. A Genuine Mercedes-Benz alternative is offered on estimate EST-2026-0014.

Labour: 0.9 hrs total per XENTRY manufacturer times (0.7 H replace V-belt + 0.2 H tensioner R&I), charged at the standard rate of £85.00 + VAT per hour.

Mobile callout: Standard callout fee (£120.00 + VAT) **waived** as a thank-you for repeat business.

Parts pricing note: FEBI parts priced at £77.26 inc VAT (tensioner) and £10.38 inc VAT (belt). Line items show ex-VAT values; total VAT shown in the totals box below.

This estimate is valid for 30 days. Final invoice will reflect actual work carried out.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.