



Invoice

Repeat Diagnostic - Exhaust / Intake Leak Investigation

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0033

STATUS

PAID

INVOICE DATE

8 May 2026

DUE DATE

N/A

PAYMENT TERMS

Paid on completion

BILL TO

Colin Carpenter

colin.carpenter@hotmail.co.uk

SERVICE ADDRESS

48 Kilby Court

Greenroof Way

Greenwich, London

SE10 0PY

48 Kilby Court

Greenroof Way

Greenwich, London

SE10 0PY

Vehicle: Mercedes-Benz Sprinter (BX69 BSV)

Odometer: -

Job ID: TPD-2026-0033

PO: -

Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
REPEAT DIAGNOSTIC VISIT (FOLLOW-UP TO TPD-2026-0021)			

Diagnostic Labour - Leak Investigation

Return visit following DPF replacement (invoice TPD-2026-0021).

Includes:

- Exhaust system pressurised smoke test (15 min soak, borescope inspection)
- Intake system pressurised smoke test
- Running-engine inspection; leak localised to LH engine bay
- EGR circuit assessment and elimination
- Advisory: oil contamination noted on LH exhaust heat shield

2
hrs £85.00 £170.00

Subtotal £170.00

Discount None (no callout fee on repeat visit)

VAT (VAT Exempt) £0.00

Total £170.00

Amount paid £170.00

Balance due **£0.00**

Payment

Settled.

✓ Paid in full by Visa debit card •••• 6478 on 23 May 2026 at 15:54. Thank you!

Stripe payment ID: pi_3TaGwiRzrswjZPkV17RH8UjF

Follow-up to invoice TPD-2026-0021 (DPF replacement): Return diagnostic visit to investigate reported leak / driveability concerns post-repair.

Works carried out: Exhaust system pressurised smoke test performed (15 minute soak, borescope inspection); intake system pressurised smoke test; running-engine inspection with leak localised to the LH engine bay; EGR circuit assessed and eliminated as the source. **Advisory:** oil contamination noted on LH exhaust heat shield.

This invoice: 2.0 hrs diagnostic labour at £85.00 per hour = £170.00 total. **VAT exempt.** No mobile callout fee on repeat visit.

Payment: £170.00 received in full on 23 May 2026 at 15:54 via Stripe (Visa debit **** 6478, NatWest). Invoice settled.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.