

Quarterly Maintenance Report

The cooling loop was inspected on March 3.

Pressure held steady at 42 psi for six hours.

Two seals were replaced on pump unit seven.

The next inspection is scheduled for June 12.

Safety Notice

All operators must wear hearing protection.

The east corridor remains closed for repairs.

Report any spill to the shift supervisor.

Emergency exits are checked every Monday.