THINGS TO CHANGE

- Not Big enough for the circuit board
- Overall mouse is too small
- Trigger relief slots rest right on thumb (slide back)
- Make trigger slots rounder (too small)
- Make back mound smoother/more angled