JD'S Automotive

9550 N 90th St Suite C-104 Scottsdale, AZ. 85258

Phone: 480-314-9845 Fax: 480-840-1513

INVOICE

1416

Org. Est. # 000471

Date: 05/05/2017

INVOICE

Griffth, John #345

8384 E Solano Dr Scottsdale, AZ 85250 2004 Chevrolet - TrailBlazer - 4.2L, In-Line6 (254CI) VIN(S)

Lic #: ASW6670 - AZ Odometer In: 156191

VIN#:1GNDT13S3 42392467

Home: 602-312-3262				VIN#:1GND113S3 42392467			
Part Description		Qty	Sale	Ext	Labor Description	Ext	
PR-EACH/BX-4 / Spark Plug		6.00	7.02	42.12	Diagnose engine misfire	47.50	
DIRECT IGN COIL / Direct Ignition Coil		1.00	77:65	77.65	Symptoms: Engine is misfiring/lacks power		
DECARB, 44K CLEANER 206/210		1.00	59.95	59.95	SPARK PLUGS - Remove & Replace - In-Line6 152.0		
OIL FILTER		1.00	2.65	2.65	IGNITION COIL - Remove & Replace - In-Line6 One -	ne - 0.00	
ENGINE OIL		7.00	2.34	16.38	[Includes: Component test.]		
Radiator		1.00	206.30	206.30		70.00	
EXTENDED COOLANT		1.50	18.95	28.43	Decard throttle body and air intake system.	7.77	
Shop Supplies				21.44	Lubricate and check chassis. Change oil and oi filter and breather filter. Check all fluid levels an Preform basic safety inspection. Road test vehi Fluid Capacity: Engine Oil - Volume: 7.00 QTS. (6.6L) - API - SA - (Note: Use oil that meets GM Standard GM60S For areas of extreme cold, where temperatures (-29Deg.C), it is recommended a SAE 5W-30 sy 0W-30 oil. Both will provide easier cold starting a for your engine at extremely low temperatures.)	d tire pressures. cle. E 5W-30; 4.2L Eng H4M. fall below -20Deg.F nthetic oil or a SAE and better protection	
					RADIATOR - Remove & Replace - In-Line6 - [Incleace - Recover, Evacuate and Recharge Air Conditionin System.] Environment Fee	udes: 361.00 g 2.00	
					Taxes		
					State Tax	28.66	
					City Tax	7.98	
					1		

Org. Estimate	50.53	Revisions	1,058.39	Current Estimate	1,108.92	Labor:	638.27
Revision # 1, Previo	ous Estimate An	nount: 50.53, Additio e - 5/2/2017, Time - 2	onal Cost: 428.88, 2:57 PM, Initiated B	Revised Estimate: 479.41, Pa By - Shop	arts: \$179.72 Labor: \$222.00 Sublet: \$0.00 Taxes & Fees: \$27.16	Parts:	454.92
Revision # 2, Previo Authorized by - Grif	Revision # 2, Previous Estimate Amount: 504.31, Additional Cost: 629.51, Revised Estimate: 1133.82, Parts: \$234.73 Labor: \$361.00 Sublet: \$0.00 Taxes & Fees: \$33.78 Authorized by - Griffth , John , Date - 5/4/2017, Time - 4:22 PM, Initiated By - Shop					HazMat:	2.00
						SubTotal:	1,095.19
						Tax:	36.64
						Total:	1,131.83
[Payments -]						Bal Due:	\$1,131.83

Vehicle Received: 5/5/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.