

```
(u0_mac_c_phy_ack ≤ u0_mac_D_phy_ack) &&  
u0_mac_c_obs_ack ≤ u0_mac_D_phy_ack
```

```
u0_mac_phy_ack?
```

```
u0_mac_phy_command_pending = false,  
u0_mac_phy_ack_timeout = false, u0_bus_schedule_open =  
false, u0_mac_obs_ack_active = false
```

PHY acknowledged

Idle

WaitPHYAck

```
u0_mac_c_phy_ack ≤ u0_mac_D_phy_ack
```

```
(u0_mac_c_phy_ack = u0_mac_D_phy_ack) &&  
u0_mac_c_obs_ack ≤ u0_mac_D_phy_ack
```

```
u0_mac_phy_ack_timeout = true, u0_mac_macReason =  
u0_mac_REASON_PHY_ACK_TIMEOUT,  
u0_mac_mac_report_pending = true,  
u0_mac_phy_command_pending = false,  
u0_bus_schedule_open = false, u0_mac_obs_ack_active =  
false
```

ack timeout

ScheduleFailure