1 River Eye PPA Analisys Report

This is an automatically generated report by the RiverEye API, `http://www.rivereye.com` the following are APP reports on each of the user select regions.

1.1 Area 1

GPS Coordinates: 23.5558° S, 46.6396° W
PPA Irregular Area: 2 ha
River Area: 1 ha
Vegetation Area: 2 ha
Non Vegetation: 5 ha
Total Area: 10 ha
Cost $ / ha: 20000

Estimated Cost: $ 40000

1.2 Area 2

GPS Coordinates: 23.5558° S, 46.6396° W
PPA Irregular Area: 2 ha
River Area: 1 ha
Vegetation Area: 2 ha
Non Vegetation: 5 ha
Total Area: 10 ha
Cost $ / ha: 20000

Estimated Cost: $ 40000

2   Recommended Deflorestation Services:[1]

- Green Sao Paulo - Website: `https://greensaopaulo.com.br/` - Rua Evans, 627, Vila Esperanca, Sao Paulo/SP, CEP: 03648-020 - (11) 94330-4540 - contato@greensaopaulo.com.br

- BioFlora Comercial - Website: `http://www.viveirobioflora.com.br/` - Rod. Piracicaba, Piracicaba/SP, CEP: 13420-280 - (19) 3414-4763 - vendas@viveirobioflora.com.br

- Forte Florestal - Website: `https://forteflorestal.com/` - Av. Vitorio Ongaratto, 926, Sala 04 Jacupiranga/SP, CEP: 11940-000 - (11) 96905-0354 - atendimento@forteflorestal.com.br

- Dantas Ambiental - Website: `https://dantasambiental.com.br/` - Rua Napoleao Selmi Dei, 676, Sala 02, Vila Harmonia, Araraquara/SP, CEP: 14802-500 -
(11) 99789-0543 - comercial@dantasambiental.com.br

- Programa Nascentes - Website: `http://www.programanascentes.sp.gov.br/`

---

[1]For illustration only