3.2.5. Clean Antistatic Bar

Estimated Frequency	Estimated Time	Press Down	Suggested Personnel	
Weekly	15 minutes for both PEMS	YES	1 person	
Objective				

Dust or dirt around the ionization points will reduce the effectiveness of the anti-static bar. The ionization points must be cleaned periodically to prevent deposits from accumulating. Dirt on the antistatic bar reduces the power delivered.

	Personal Protective Equipment (PPEs)	Tools/Materials	
		Dry compressed air	
□ None	None	Soft, long-bristled brush	
	None	Mirror with handle	

NOTE: Never use hard or sharp objects to scrape ionization points.



CAUTION: ELECTRICAL SHOCK HAZARD— De-energize all powersupplies before performing any maintenance tasks.

Procedure

- 1. Use dry compressed air to remove loose particulate from the static bar.
- 2. If the antistatic bar is very dirty you may need to use a brush.



Figure 11. Antistatic bar