# Flange observation

| RECORD / DATE | ASSET / JOB |
|---|---|
| DOC-001 / 2026-09-18 | MC01-P17 / MC-J104 |
| STATUS | SOURCE |
| Inspection requested | Fictional maintenance collection |

## Observation

A white mineral crust was visible around the lower flange of the green heating circulation pump with the orange pipe band. A small damp patch was visible on the floor directly below. The observation does not identify the source or cause of moisture.

## Asset and location

Asset MC01-P17, east heating bay, Mercer Court basement plant room. Reference photograph IMG-039 and recording AUD-001 were captured for this visit. The blue-band pump MC01-P01 is a separate asset.

## Follow-up

Job MC-J104 requests contractor assessment. No isolation method, operating setting or replacement specification is supplied. No work was carried out by the visiting manager.

## Record boundary

This report records the condition seen on 18 September only. It does not state the current condition. Photos in this corpus are independently invented; no other photograph is claimed to be a later view of this exact pump.