# Pump follow-up history

| RECORD / DATE | ASSET / JOB |
| --- | --- |
| DOC-003 / 2026-10-06 | MC01-P17 / MC-J104 |
| STATUS | SOURCE |
| Limited visual follow-up | Fictional maintenance collection |

## Follow-up visit

On 6 October the visiting manager recorded no visible fresh dampness beneath MC01-P17 from the walkway. Recording AUD-014 contains that limited observation. No new photograph was taken.

## Historical entries

18 September: white deposits and dampness observed. 22 September: contractor recorded gasket replacement and a dry completion check. These dates describe different records and should remain visible in search results.

## Limits

Absence of visible dampness during one visit does not establish a permanent repair. The old image IMG-039 should not be presented as proof of a current leak. The search application retrieves sources and does not determine condition.

## Next handover

Retain the original observation, contractor entry and follow-up together under MC01-P17. A future visiting manager should create a new dated record if there is another observation.