Pipe insulation observation

RECORD / DATE	ASSET / JOB
DOC-005 / 2026-09-27	MC01-I01 / MC-J113
STATUS	SOURCE
Awaiting contractor date	Fictional maintenance collection

Visible condition

A seam in the silver foil jacket on the purple-band pipe had separated, exposing pale insulation. No touching, removal or material identification was carried out. Sources IMG-041 and AUD-005 belong to this visit.

Location

Asset MC01-I01, pipe corridor in the Mercer Court basement. This is an insulation condition record rather than a confirmed leak. The photograph alone cannot establish the material composition.

Work status

Job MC-J113 is open and awaiting a contractor date as of 27 September. There is no completion entry in this demonstration collection. No repair method is supplied.

Similar record elsewhere

Calder House asset CH02-I01 concerns torn black foam around a dry copper bend. It is another building and another asset; it must not inherit this work-order status.