Upper connection observation

RECORD / DATE	ASSET / JOB
DOC-009 / 2026-09-20	CH02-P12 / CH-J203
STATUS	SOURCE
Inspection requested	Fictional maintenance collection

Observation

White deposits and a small damp floor patch were recorded at the upper connection of blue-band green pump CH02-P12 in Calder House rear heating bay. Sources IMG-088 and AUD-016 record the observation.

Asset distinction

The orange-band green pump CH02-P01 is another Calder House asset and was recorded as dry in AUD-015. Mercer Court MC01-P17 has a separate lower-flange incident. None of these identities are interchangeable.

Work status

Job CH-J203 requests a qualified contractor inspection. This pack contains no completion record for the job. The observation does not identify the source of the water or the failed component.

Use of evidence

Show the building and capture date with each result. No operating instructions, isolation method or replacement specification are included. An image match alone is not a confirmed asset identification.