Northbridge Lettings

# Checkout inspection report

To record the condition and cleanliness of Flat 30, 30 Harbour View, Northbridge, ZZ9 0ZZ, at checkout and compare it with a previous inspection.

---

Title: Checkout inspection report. Appointment date: 16 March 2026. Assessor: Northbridge Lettings.

The report describes the inspected property room by room, records its contents where present, and identifies observed defects with supporting photographs. It is a visual inspection; inaccessible and loft areas are not inspected. The report does not necessarily identify structural defects, give repair advice or costs, or confirm that fixtures and fittings work. Descriptions such as silver, chrome or oak refer to appearance and do not necessarily identify the material. The report belongs to the instructing party and may not be used without written permission.

Checkout guidance: the property and contents are expected to be in a similar condition and cleanliness to the report prepared before the tenancy. Damage beyond fair wear and tear may need repair or replacement, with costs potentially deducted from the tenant’s deposit; receipts should be retained. If cleaning is unsatisfactory, a professional cleaner may be instructed and the cost potentially deducted from the deposit. Cleaning should be thorough and the property left tidy. Carpets and curtains should be professionally cleaned where required by the inventory or tenancy agreement. Vinyl or tiled floors should be clean and free from cracks or tears. Decor should match the earlier report; added picture hooks, nails, screws and holes may need removal or repair, and excessive marks and fingerprints should be cleaned. Refrigerators and freezers should be defrosted, switched off and left open. Ovens, hobs, extractors and microwaves should be cleaned, including burnt deposits, grease, doors and seals. Gardens, where applicable, should be left tidy, with lawns cut and borders, planters, hedges, paths and patios maintained. Smoke and carbon monoxide alarms were checked and recorded as working on the report date; the tenant is responsible for keeping them working and reporting faults, other than battery replacement.

Rating definitions—condition: Excellent means unused or new; Good means minor wear without obvious appearance or function faults; Fair means wear or minor damage; Poor means extensive wear such as stains, marks, rips or chips; Unacceptable means not fit for purpose, such as badly damaged or faulty. Cleanliness: Excellent means cleaned to a high standard; Good to a good standard; Fair to a fair standard; Poor means light cleaning required; Unacceptable means professional cleaning required. Item cleanliness ratings refer to the issues and photographs.

Bedroom, current report: grey carpet requires cleaning and has patches of grease and other stains; furniture requires light cleaning; small amounts of dumped items are present; there is evidence of smoking; dust and dirt are behind the bed; the door handle has failed and requires replacement. Condition rated Poor; cleanliness rated Unacceptable.

Bedroom, previous report: grey carpet, cream painted walls, white radiator, television and hinged mount, wardrobe and two-drawer unit, three-quarter double bed and headboard, silver sockets and switches, ceiling spotlight and functioning bulbs, chair and table, television remote, UPVC window and vertical blinds were recorded as generally in good clean condition. The mattress was in poor condition with various stains.

Bathroom, current report: door in good clean condition; window and blinds in good condition; cream painted walls in fair condition with some marks; sink, shelving, vanity unit, shower screen, shower equipment and bathing equipment require cleaning; dumped items are present; toilet roll holder is damaged. Condition and cleanliness rated Unacceptable.

Bathroom, previous report: wooden-effect vinyl floor, close-coupled WC and plastic seat were in good/clean condition. Cream painted walls had very minor marks. White ceramic sink and mixer tap were in fair condition, with limescale on the tap. Under-sink cupboard, shower screen, plastic bath and clad plastic walls were in good clean condition. Bath mixer taps and shower equipment were in good clean condition with very minor limescale marks. Towel radiator, white plastic bin,

vertical blinds and ceiling were in good clean condition; the new PVC window had some cobwebs. Lamp and extractor fan were recorded as working.

Meters: electricity readings were recorded as not applicable because electricity was included in rent, both in the previous and current reports.

Keys: the report has previous and current date rows, but no key details or comments are recorded.

Detectors: the site-wide system was tested by staff and marked Yes in both the previous and current reports. The current report was signed as reflecting the assessor’s assessment on 22 July 2025 at 11:39:13.

| Report | Inspection area | Condition | Cleanliness | Defects | Photographs | Tenant comments |
|---|---|---|---|---|---|---|
| Previous, 29 November 2024 | Bedroom | Good | Good | 0 | 33 | 0 |
| Previous, 29 November 2024 | Bathroom | Good | Good | 0 | 24 | 0 |
| Current, 16 March 2026 | Bedroom | Poor | Unacceptable | 3 | 24 | None recorded |
| Current, 16 March 2026 | Bathroom | Unacceptable | Unacceptable | 4 | 31 | None recorded |

| Date | Condition | Cleanliness | Description and issues |
|---|---|---|---|
| 29 November 2024 | Good | Good | Grey carpet, cream painted walls, white radiator, television and hinged mount, wardrobe and two-drawer unit, bed and headboard, sockets and switches, ceiling spotlight with functioning bulbs, chair and table, television remote, UPVC window and vertical blinds generally recorded in good clean condition. Mattress recorded in poor condition with various stains. |
| 16 March 2026 | Poor | Unacceptable | Grey carpet requires cleaning and has patches of grease and other stains; furniture requires light cleaning; small amounts of dumped items present; evidence of smoking; dust and dirt behind bed; failed door handle requires replacement. |

| Date | Condition | Cleanliness | Description and issues |
|---|---|---|---|
| 29 November 2024 | Good | Good | Wooden-effect vinyl floor and close-coupled WC with plastic seat in good/clean condition; cream painted walls had very minor marks; sink and mixer tap fair with limescale; under-sink cupboard, shower screen, bath and clad walls, bath taps and shower equipment, towel radiator, bin, blinds and ceiling generally in good clean condition. PVC window had some cobwebs; lamp and extractor fan recorded as working. |

| Date | Condition | Cleanliness | Description and issues |
|---|---|---|---|
| 16 March 2026 | Unacceptable | Unacceptable | Door in good clean condition; window and blinds in good condition; cream walls fair with some marks; sink, shelving, vanity unit, shower screen, shower equipment and bathing equipment require cleaning; dumped items present; toilet roll holder damaged. |

| Report date | Utility | Reading | Location | Serial number | Supply type |
|---|---|---|---|---|---|
| 29 November 2024, previous | Electricity | Not applicable — included in rent | | | |
| 16 March 2026, current | Electricity | Not applicable — included in rent | | | |

| Report date | Details | Tested | Comments |
|---|---|---|---|
| 29 November 2024, previous | Site-wide system tested by staff | Yes | |
| 16 March 2026, current | Site-wide system tested by staff | Yes | |

| Report date | General key details | General key comments |
|---|---|---|
| 29 November 2024, previous | | |
| 16 March 2026, current | | |

# Observations

- The previous report is dated 29 November 2024 and the current report is dated 16 March 2026.
- The report summary records the bedroom as Good condition and Good cleanliness previously, changing to Poor condition and Unacceptable cleanliness currently. It records the bathroom as Good for both previously, changing to Unacceptable condition and cleanliness currently.
- The current summary counts 3 bedroom defects and 4 bathroom defects. It lists 24 bedroom photographs and 31 bathroom photographs. The previous summary lists 33 bedroom photographs and 24 bathroom photographs.
- The report lists no tenant comments for the previous bedroom and bathroom entries; current tenant-comment fields contain no substantive comment text.
- The checklist, external-area descriptions and notes pages contain no recorded details.
- The report contains one previous-report detector photograph.

# Findings

- Bedroom defects: carpet, furniture and failed door handle.
- Bathroom defects: areas to clean, dumped items, paintwork defects and broken toilet roll holder.
- The bathroom inspection description states the toilet roll holder is damaged; the defect list describes it as broken.
- The report records evidence of smoking in the bedroom and dust and dirt behind the bed.
- The report records small amounts of dumped items in the bedroom and dumped items in the bathroom.

## Conclusions

- At the current inspection, both the bedroom and bathroom required attention. The bedroom was rated Poor for condition and Unacceptable for cleanliness; the bathroom was rated Unacceptable for both.
- The report identifies cleaning requirements, dumped items and specific maintenance defects, including the failed bedroom door handle and damaged bathroom toilet roll holder.

## Image evidence

**Neutral image placeholder**

Cover photograph: exterior entrance and approach to the inspected building.

**Neutral image placeholder**

Previous-report detector photograph: ceiling-mounted detector shown as visual context for the detector record.

**Neutral image placeholder**

Current bedroom photo 1 of 24: bedroom overview showing the door, wall and radiator.

**Neutral image placeholder**

Current bedroom photo 2 of 24: general view of the bedroom furnishings and room layout.

**Neutral image placeholder**

Current bedroom photo 3 of 24: bedroom floor and furniture in context.

**Neutral image placeholder**

Current bedroom photo 4 of 24: general overview of bedroom fixtures and furnishings.

**Neutral image placeholder**

Current bedroom photo 5 of 24: general overview of the bedroom.

**Neutral image placeholder**

Current bedroom photo 6 of 24: general overview of the bedroom.

**Neutral image placeholder**

Current bedroom photo 7 of 24: general overview of the bedroom.

**Neutral image placeholder**

Current bedroom photo 8 of 24: general overview of the bedroom.

**Neutral image placeholder**

Current bedroom photo 9 of 24: general overview of the bedroom.

**Neutral image placeholder**

Current bedroom photo 10 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 11 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 12 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 13 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 14 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 15 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 16 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 17 of 24: carpet detail recorded under the carpet defect.

**Neutral image placeholder**

Current bedroom photo 18 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 19 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 20 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 21 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 22 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 23 of 24: furniture detail recorded under the furniture issue.

**Neutral image placeholder**

Current bedroom photo 24 of 24: close view of the failed bedroom door handle.

**Neutral image placeholder**

Current bathroom photo 1 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 2 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 3 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 4 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 5 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 6 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 7 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 8 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 9 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 10 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 11 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 12 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 13 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 14 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 15 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 16 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 17 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 18 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 19 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 20 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 21 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 22 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 23 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 24 of 31: bathroom area identified for cleaning.

**Neutral image placeholder**

Current bathroom photo 25 of 31: dumped items recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 26 of 31: dumped items recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 27 of 31: dumped items recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 28 of 31: paintwork defect recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 29 of 31: paintwork defect recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 30 of 31: paintwork defect recorded in the bathroom.

**Neutral image placeholder**

Current bathroom photo 31 of 31: damaged toilet roll holder.