

arxdsilva
@arxdsilva

A modified update won't root this car. Neither will its shell command.

Rasmus Moorats only wanted to fix the clock on his 2014 Renault.

Two bugs that looked harmless got him root together.





arxdsilva
@arxdsilva

Three plans, per his write-up.

Which would you try first? Save this.

- Patch the update image: a signature check blocked it.
- Use the script's shell command: one token, noexec mounts.
- Works: a log bug set core_pattern, a crash ran his script.