


Arx


Sheet: /2-Power/
File: 2-Power.kicad_sch


Title: Power Supply and Opamp Biasing


Size: A4 Date: 2024-03-12 Rev: 3.1


KiCad E.D.A. 8.0.5 Id: 2/5














Battery spring pushing against enclosure. Can be used as a single point of grounding.

One point of contact with enclosure is ideal, but we can also use two (spring and mounting hole + pad + metal standoff).

GROUNDING SPRING





what's missing: — knobs for pots

Arx		
	ountingAndAccessories/ tingAndAccessories.kicad_sch	
Title: Mou	nting, hardware and accessories	•
Size: A4	Date: 2024-03-12	Rev: 3.1
KiCad E.D.A. 8.0.5		ld: 5/5