Surface Developmenti. Darelopment of prisms: Me-draw the given views. Val Mark 1,2,3. . on the top view " 1,2,3' ... on the base of F.v. E) Mark pig', r'... on the F.V 2) Draw Sectional T.V. a) Draw horizontal line from center of Tv.
b) Draw vertical lines from p'a', r'... to T.V.
you get P.a. then join them and draw
hatching lines inside it. 3) Draw 'True shape' of section: a) Draw a time parallel to cutting plane line and perpendicular lines from p',q',r'... b) Mark P. 9. r amording to sectional T.v. then join them and draw hatching lines inside it 1) Draw Surface development. a) Draw horizon as lines from base and top of F.V. y) Mark 1,2,3... on the base line according to Side length of T.V.

() Draw vertical lines from 1,2,3 -- and horizon 121 lines from p',q',r'... you get p,q,r... then join them d) Draw bottom cover. e) Draw top cover.



