

Survey Summary

The categories of survey performed by us can be broadly categorized into 3 main parts:

1. Performing the Traffic Volume Survey: The manual counting method was adopted to calculate the In-Situ conditions of road regarding its usage. The road was fairly busy during Weekdays as well as Weekends with nearly 2500-3000 vehicles crossing the intersection, on an average. Taking the concept of *PCU* & *PCE* in mind, the volume came out to be nearly 1250-1500 vehicles per hour.
2. Survey of the Stretch: The survey of the stretch was performed in order to identify the existing Traffic Control Devices (mainly Signs and Markings) and to add as well as replace, if needed. The need of the traffic control devices at their respective locations in detail have already been discussed in the report of Phase IV.
3. Survey of the Stakeholders: A survey of the stakeholders had also been carried out, which in tabular format is mentioned as follows:

Categories of Stakeholders interviewed and their respective quantity: -

➤ Private Vehicle Owner:	4
➤ E- Rickshaw Driver:	4
➤ Shopkeeper:	5
➤ Street Vendor:	7
➤ Policemen:	2
➤ Ambulance Driver:	1
➤ School Guard:	1
➤ Doctor:	1
➤ Auto Rickshaw Driver:	2

Total stakeholders interviewed: 28

Multiple persons from each of the category were interviewed during our detailed survey by the team members. An aggregate of approximately 25-30 persons were selected for the survey and the table show almost one from each of the category. There were some more of the categories (like Ambulance Driver, E-Rickshaw Driver, Policeman from the Police Station having the jurisdiction.). Although, these persons were too having almost the same kind of problems which are already listed out in the chart

.

Questions for Survey for 5 of the given categories is as given below:

S.No.	Survey Questions	P1	P2	P3	P4	P5
1	Profession	Shopkeeper	Watchman	Juice Seller	Policeman	House lady
2	Age	37	40	23	43	33
3	Travelling Frequency via Spot	Daily	Daily	Daily	Daily	Once in a week. On an average
4	Problems faced on this road related to Road Safety	Road Congestion by vendors, Lack of information regarding Road Markings	Congestion of road in front of School	Open Sewer, Congestion	Lack of Awareness, Rash Driving, Bike Stunts in night time	Parking Issue, Blurred markings and lack of marking info
5	Evident of any Accident	Yes	-----	-----	Yes, many were unreported	No
6	Speed Limit	-----	-----	-----	-----	20-30kmph
7	Should Road Markings be re-marked	Yes	Yes	Yes	Yes	Yes
8	Should Banner be installed for the information regarding Traffic Signs & Markings	Yes	-----	-----	Yes	Yes
9	Is proper Lighting present at the Site	Yes	Yes	-----	Yes	Yes

The recommendations of other people were almost same to these mentioned above.

So, this was all about the surveys carried out by the Team...