



STEPS FOR WORKING IN KIEL μ VISION S/W FOR 8051 IN LAB

- ❖ CREATE A FOLDER WITH YOUR REGISTRATION NUMBER IN DESKTOP
- ❖ REPEAT THE FOLLOWING STEPS INSIDE YOUR FOLDER BY CREATING SUB-FOLDERS
- ❖ FOR EVERY TASK ASSIGNED SUBMIT THE DATA BY THE NEXT WORKING WEEK


1. OPEN KIEL μ VISION5 IN DESKTOP. (IF ANY EXISTING PROJECT IS OPENED, CLOSE THE PROJECT SO THAT A GREY SCREEN APPEARS)
2. GOTO PROJECT-NEW μ VISION PROJECT (GIVE A NAME & SAVE IN YOUR FOLDER)




3. SELECT DEVICE (LEGACY DEVICE DATABASE...) AND SEARCH NAME OF MICROCONTROLLER YOU WILL BE USING (P89V51RD2)




4. START UP51-ASSEMBLER...CLICK OK AND YES (NAME APPEARS)




5. CREATE EMPTY DOCUMENT TYPE AND STORE YOUR PROGRAM WITH EXTENSION **.asm**




6. ATTACH THE FILE TO THE ASSEMBLER




7. TRANSLATE-BUILD-REBUILD (FOR CHECKING SYNTAX ERROR AND LINKING FILE WITH ASSEMBLER)



8. DEBUG AND CHECK FOR RESULTS





FOR STEP BY STEP EXECUTION

- NOTE THE RESULT AND TAKE SCREENSHOT AND SAVE IT WITH YOUR NAME AND LAB_PROJECT_NO

OTHER RESULT WINDOWS

