
landing controller removed
home view memory removed
heading ring removed (Study 1 compass)
heading ring swapped for Kalman filter
insect front end removed
evidence gating removed
inspection rule removed
sensitivity arms
learning flight 0 s (calibrated with flight)
no operator tip
poor operator tip
0.849
0.645
0.110
0.047
0.030
0.020
-0.004
0.852
0.098
0.018
0.0
0.2
0.4
0.6
0.8
1.0
AUC lost (full brain minus arm)