
Delta from prior command
Delta from measured pose
Toy measured position (mm)
0
20
40
60
80
0
2
4
6
8
10
Toy control tick