
Mean = 0 deg; RMSE = 1.414 deg
Measured − command (deg)
2
0
−2
1
2
3
4
Sample index