Northwest Geophysical Associates

Appendix A

IN-LINE CSAMT SURVEY ON THE AFEK PROJECT

Golan Heights

Prepared for:

Genie Oil and Gas Company

November 14, 2013

NGA Job# 13060

Appendix A

Production Schedule and Line Statistics

Date	Day	Production Hours	Standby Hours	Notes
06/09/13	Fri			Nordstrom travels.
07/09/13	Sa			Nordstrom travels.
08/09/13	Su			Nordstrom: Meeting in Jerusalem; drive to Golan. Crew travels (apprx 13.5 hrs)
09/09/13	Mo			Nordstrom: Preparations in Qatzrin; prep MG set; test with pick-up. Crew travels (appx. 10.50 hrs).
10/09/13	Tu			Nordstrom: Preparations; look MG trailer; purchase supplies
11/09/13	We	9.00		Move to Dishon- preparing equipment; check receivers.
12/09/13	Th	10.50		Surveyed first two lines; locate transitter A, but landowner problems; build receiver wires.
13/09/13	Fri		10.0	Holiday
14/09/13	Sa			Day Off; Sabbath.
15/09/13	Su	10.50		Move out of Dishon; company meeting in Qatzrin; Read data on Lines A3 and A4.
16/09/13	Mo	11.00		Read Lines A1 and A2; pick up Tx A; built Tx B; GPS on Lines B1 and B2; permit problems on B3.
17/09/13	Tu	11.50		Read Lines B1, B2, B3; noisy data on B2; build Tx H; GPS Lines HW1 and HE8. .
18/09/13	We	7.50		Finish building Tx H; repair wires from cattle damage; read Lines HW1 and HE8; GPS Lines HW2, HW3, HW4, HE5, and HE7.
19/09/13	Th		10.0	Holiday
20/09/13	Fri	7.00		Read Lines HE5, HE6. HE7; scout new HW2; locked gate for HW3 and HW4; GPS TX I.
21/09/13	Sa			Day Off; Sabbath.
22/09/13	Su	11.00		Read Lines HW2, HW3, HW4, I1, I2
23/09/13	Mo	11.00		Pick up Tx I, put in Tx C2; read Lines C2-3, C2-6, C2-4, C2-5.
24/09/13	Tu	12.00		Pick up Tx C2, install Tx C3; read Lines C2-1, C2-2, C3-7, C3-8, C3-9; windy; belt

				problem on MG set.
25/09/13	We	7.50		Install Tx E1 (short due to locked gates); Read Lines E1S-1, E1S-2, E1S-3, E1S-4; MG belt problem fixed.
26/09/13	Th		10.0	Holiday
27/09/13	Fri	7.00		Read Lines E1N-5, E1N-6, E1N-7, E1N-8; pick up Tx E-1; pick up Tx-H.
28/09/13	Sa			Day Off; Sabbath.
29/09/13	Su	12.00		Install Tx E2; read Lines E2-3, E2-4, E2-5, E2-6, E2-7.
30/09/13	Mo	12.00		Pick up Tx E2; Install Tx D; Read lines E2-1, E2-2, D-1, D2; truck problems.
01/10/13	Tu	10.00		Pick up Tx-D; install Tx-K4; read Lines D-3, D-4; pick up Tx-K4 due to military activity.
02/10/13	We	8.50		Re-install Tx-K4; read Lines K4-11 and K4-12.
03/10/13	Th	2.00	8.0	Preparation for broadside/vector measurements; Nordstrom scouts locations for broadside CSAMT.
04/10/13	Fri		10.0	Campbell and Huerstel pick up Tx-K4; Waiting on coils.
05/10/13	Sa			Day Off; Sabbath. Reduction in crew size beginning today.
06/10/13	Su			Waiting on coils.
07/10/13	Mo	11.50		Install Tx-L; read Lines L-3 and L-5.
08/10/13	Tu	10.00		Install Tx-M; Read Broadside Lines M1 and M2; pick up Tx-M.
09/10/13	We	9.50		Read Lines L-1 and L-2; pick up Tx-L.
10/10/13	Th	9.50		Install Tx-N; read Lines N-3, A-2, and A-4 from Tx-N.
11/10/13	Fri		10.0	Preparations for MT soundings.
12/10/13	Sa			Day Off; Sabbath.
13/10/13	Su	10.00		Install Tx-P; remove due to permit problem; re-install; read Lines P-1, P-2, and P-3; remove Tx-P.
14/10/13	Mo	10.00		Install Tx-Q; read Lines Q-1, Q-2, Q-3; remove Tx-Q; install remote reference MT site.
15/10/13	Tu	9.00		Clean and prepare equipment for shipping; begin MT-1 and MT-2 soundings.
16/10/13	We	8.00		Read MT-1 and MT-2; pick up MT-1 and MT-2, install MT-3, MT-4. Problems with remote reference site.
17/10/13	Th	6.00		Pick up MT-3, MT-4; install MT-5, MT-2R; clean and pack equipment for shipping.
18/10/13	Fri	4.50		Pick up MT-5, MT-2R; finish packing equipment.
19/10/13	Sa			Day Off; Sabbath.

20/10/13	Su			Crew Travels to Tel Aviv; Leave for Tucson.
21/10/13	Mo			Crew arrives Tucson.
Total to Date:	248.00	58.00		