

Document Title: AeroCam Mini 2 Service Handbook

Product Series: AeroCam

Product Model: AeroCam Mini 2

Document Type: Service Handbook

Language: en-US

Version: 3.1

Release Date: 2026-06-12

Source URL: <https://example.com/support/aerocam-mini-2/service>

A fictional compact aerial imaging product used only for governance tests.

Use the model identifier before selecting a maintenance procedure.

Flight system maintenance

Run propeller calibration after replacing a motor or vibration damper.

Inspect the battery latch before enabling coastal wind compensation.

Record the calibration result together with this page number.

Firmware diagnostics

Supported firmware range: 2.4.0 through 2.9.x.

Error code AM2-17 indicates that the gimbal home sensor needs inspection.

Do not apply procedures written for AeroCam Pro 2.