

Thinsulate wrap removed from the ring: room error below 3 kHz 2.219 → 2.205 dB (-0.014, better)

2026-09-24/wall-direct-absorber → 2026-09-24/ring-bare · below 3 kHz, 376 of 946 cells moved >0.05 dB toward flat and 386 away from it · 95 tones · 11 calibrated capsules

