

Metal rod placed in the chamber: room error below 3 kHz 2.509 → 2.506 dB (-0.003, same)

2026-09-24/carpet-plus-felt → 2026-09-24/metal-rod · below 3 kHz, 316 of 946 cells moved >0.05 dB toward flat and 339 away from it · 95 tones · 11 calibrated capsules

