

Felt carpet (~2 cm) added on the floor, Thinsulate still on the ceiling: room error below 3 kHz 1.424 → 1.457 dB (+0.033, worse)

2026-09-24/ceiling-carpet-day2 → 2026-09-24/ceiling1-floor2 · below 3 kHz, 414 of 946 cells moved >0.05 dB toward flat and 452 away from it · 95 tones · 11 calibrated capsules

