

Speaker moved from the wall reinforcement to the wall itself, further from the ring: room error below 3 kHz 2.109 → 2.170 dB (+0.061)

2026-09-24/wall-mount-decoupled → 2026-09-24/wall-direct-a · below 3 kHz, 385 of 946 cells moved >0.05 dB toward flat and 526 away from it · 95 tones · 11 calibrated capsules

