

Metal rod removed (felt on floor and ceiling): room error below 3 kHz 2.051 → 2.054 dB (+0.003, same)

2026-09-24/felt-ceiling → 2026-09-24/rod-removed · below 3 kHz, 205 of 946 cells moved >0.05 dB toward flat and 171 away from it · 95 tones · 11 calibrated capsules

