

The ceiling felt laid on the floor: room error below 3 kHz 2.107 → 2.517 dB (+0.409, worse)

2026-09-24/ceiling-felt-removed → 2026-09-24/ceiling-felt-to-floor · below 3 kHz, 294 of 946 cells moved >0.05 dB toward flat and 618 away from it · 95 tones · 11 calibrated capsules

