

Felt and foam placed behind the wall-mounted speaker: room error below 3 kHz 2.170 → 2.219 dB (+0.049, worse)

2026-09-24/wall-direct-a → 2026-09-24/wall-direct-absorber · below 3 kHz, 455 of 946 cells moved >0.05 dB toward flat and 439 away from it · 95 tones · 11 calibrated capsules

