

Felt turned foil side into the chamber: room error below 3 kHz 2.517 → 2.753 dB (+0.236, worse)

2026-09-24/ceiling-felt-to-floor → 2026-09-24/felt-foil-in · below 3 kHz, 415 of 946 cells moved >0.05 dB toward flat and 480 away from it · 95 tones · 11 calibrated capsules

