

01 CIVIC CENTRE & LIBRARY

THE PUBLIC SPACE

A key feature is the pedestrianization of the public space:

Existing Condition of Public Space

The present road and space conditions are inconsistent.

The walking plaza of MG Road is well maintained and utilized.

However other paths on the site are very ill-maintained and dangerous to use.

There is a very weak connection between all spaces leading to a disjointed nature of pedestrian development.

Proposed Changes in Public Space

Changes seek to remove the disjointed nature of the public space and merge it with MG Marg.

Changes include rerouting Tibet road, extending pedestrianized portion of MG Marg, and making width of NH10 consistent.

