Solid Modeling 121 Mid-Term Exam

- 1. Create an assembly and begin to mate the components as shown in the Gearbox Assembly Drawing.
- 2. Model the gasket as shown on page 4.
- 3. Model the Rear Casting part.

You may want to model it using the top-down assembly method. It's much faster.

4. Re-Create Gearbox Exploded Assembly Drawing on page 2.

The drawing view and appearance must be as close as possible.





