
GO-FRUIT MAN 1 PONOROGO-7



SENSOR TCS3200

1.VCC - Raspberry Pi 5V

2.OUT - Raspberry Pi GPIO26

3.S3 - Raspberry Pi GPIO24

4.S2 - Raspberry Pi GPIO23

5.LED - Raspberry Pi GPIO22

GND - Raspberry Pi GND

SENSOR HC-SRF04

VCC - Raspberry Pi 5V

TRIGGER - Raspberry Pi GPIO6(1), GPIO25(2), GPIO16(3)

ECHO - Raspberry Pi GPIO5(1), GPIO4(2), GPIO27(3)

GND - Raspberry Pi GND

SERVO MG996R

VCC - Raspberry Pi 5V

GND - Raspberry Pi GND

SIGNAL - Raspberry Pi 17