HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-3553

Customer: Omar Xu

Vehicle: 2018 Toyota Camry

Description of repair Amount

Headlamp assembly: $933.00

Hood panel: $858.00

Radiator support: $1,125.00

Front bumper cover: $1,721.00

Shop supplies: $943.00

Total estimate: $5,580.00