EAGLE BODY & PAINT

REPAIR ESTIMATE

Estimate no.: EST-3627

Customer: Patrick Reyes

Vehicle: 2010 Audi A5

Description of repair Amount

Headlamp assembly: $923.00

Radiator support: $1,652.00

Front grille: $2,225.00

Hood panel: $2,310.00

Frame and alignment: $991.00

Shop supplies: $2,389.00

Total estimate: $10,490.00