SUMMIT COLLISION

REPAIR ESTIMATE

Estimate no.: EST-5366

Customer: Samuel Hayes

Vehicle: 2016 Honda Accord

Description of repair Amount

Fender: $3,105.00

Headlamp assembly: $908.00

Radiator support: $2,613.00

Front bumper cover: $2,192.00

Frame and alignment: $2,051.00

Paint and materials: $4,171.00

Total estimate: $15,040.00