HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-6217

Customer: Fatima Gupta

Vehicle: 2017 Accura TL

Description of repair Amount

Front bumper cover: $3,006.00

Fender: $1,704.00

Paint and materials: $1,960.00

Total estimate: $6,670.00