HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-7549

Customer: Daniel Patel

Vehicle: 2020 Mercedes C300

Description of repair Amount

Trunk lid: $626.00

Rear bumper cover: $550.00

Tail lamp assembly: $2,625.00

Rear body panel: $1,549.00

Shop supplies: $970.00

Total estimate: $6,320.00